


CIRIA C681: unexploded ordnance

4 stage risk management process for constructors



Complete the plan and

receive a verification report.

No further action required.

WAR DAN

Review the finding,

complete the plan and if

necessary, repeat stage 4.